A. PROCESS

DOE/RL-88-21 216-B-63 Trench 11/22/99 Rev. 5,

Please print or type in the unshaded areas only
(fill-in areas are spaced for elite type, i.e. 12 character/inch)

3	DAN	IGER	OUS WASTE PERMI	T APPLICATIO	N	I. EPA/STATE I.D. NUMBER W A 7 8 9 0 0 0 8 9 6 7	
FOR OFFICIA	AL USE ONLY					1	
	APPLICATION DATE RECEIVED (mo., day, & yr.) COMMENTS						
	Approved 10/30/00						
II. FIRST OR	REVISED APPLICATI	ON					
application. If	n the appropriate box this is your first applic n Section I above.	in A or B ation and	below (mark one box only) to indicate w you already know your facility's EPA/S	hether this is the first applic TATE I.D. Number, or if this	ation you are subn is a revised applic	nitting for your facility or a revised ation, enter your facility's EPA/STATE	
A. FIRST APF	PLICATION (place an EXISTING FACILITY	(and provide the appropriate date) (See instructions for definition of "existir Complete Item below.)	ng" facility.	NEW FACILITY (C	Complete item below)	
MO.	DAY YEAR		*FOR EXISTING FACILITIES, PROVIDI		DAY YEAR	FOR NEW FACILITIES, PROVIDE THE DATE, (mo., day, & yr.)	
03	22 1943		DATE (mo., day, & yr.) OPERATION BE THE DATE CONSTRUCTION COMMEI			OPERATION BEGAN OR IS EXPECTED TO BEGIN	
		•	the boxes to the left) *The date construction of the Hanford F commenced.	acility		EXPECTED TO BEGIN	
B. REVISED A	APPLICATION <i>(place</i> ACILITY HAS AN INT	an "X" be ERIM ST	elow and complete Section I above) ATUS PERMIT 2. I	FACILITY HAS A FINAL PEI	RMIT		
III. PROCESS	- CODES AND CAPA	ACITIES					
codes. If I	more lines are needed	, enter the	the list of process codes below that bes e code(s) in the space provided. If a pro the space provided on the (Section III-0	cess will be used that is not		cility. Ten lines are provided for entering to codes below, then describe the	
B. PROCES	S DESIGN CAPACITY	′ - For ea	ch code entered in column A enter the o	capacity of the process.			
	INT - Enter the amoun						
2. UNIT (OF MEASURE - For ea	ach amou	unt entered in column B(1), enter the coded below should be used.	de from the list of unit measu	ıre codes below th	at describes the unit of measure used.	
ŕ	PROCESS	PRO- CESS CODE	APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY	PROCESS	PRO CES COL	SS MEASURE FOR PROCESS	
							
Storage:				Treatment:			
CONTAINE TANK	R (barrel, drum, etc.)	S01 S02	GALLONS OR LITERS GALLONS OR LITERS	TANK	T0	1 GALLONS PER DAY OR LITERS PER DAY	
WASTE PII	LE	S03	CUBIC YARDS OR CUBIC METERS	SURFACE IMPOUND	MENT TO	2 GALLONS PER DAY OR LITERS PER DAY	
SURFACE	IMPOUNDMENT	S04	GALLONS OR LITERS	INCINERATOR	TO	3 TONS PER HOUR OR	
Disposal:						METRIC TONS PER HOUR; GALLONS PER	
INJECTION	N WELL	D80	GALLONS OR LITERS			HOUR OR LITERS PER HOUR	
LANDFILL		D81	ACRE-FEET (the volume that would cover one acre	OTHER (Use for physic	cal, T0-	4 GALLONS PER DAY OR	
			to a depth of one foot)OR	chemical, thermal or bi	ological	LITERS PER DAY	
LAND APP	LICATION	D82	HECTARE-METER ACRES OR HECTARES	treatment processes no occurring in tanks, surf			
OCEAN DI	SPOSAL	D83	GALLONS PER DAY OR LITERS PER DAY	impoundments or incin Describe the processes			
SURFACE	IMPOUNDMENT	D84	GALLONS OR LITERS	space provided: Section			
	UNIT	ΓOF		UNIT OF		UNIT OF	
UNIT OF M	MEAS		UNIT OF MEASURE	MEASURE CODE	UNIT OF MEAS	MEASURE	
						OOK OOD	
GALLONS LITERS	(L		LITERS PER DAY TONS PER HOUR	V D	ACRE-FEET HECTARE-ME	A TER F	
CUBIC YAI	RDS \	1	METRIC TONS PER HOUR	W	ACRES	В	
CUBIC ME GALLONS)	GALLONS PER HOUR LITERS PER HOUR	E H	HECTARES	Q	
	EXAMPLE FOR COMPLETING SECTION III (shown in line numbers X-1 and X-2 below): A facility has two storage tanks; one tank can hold 200 gallons and the other can hold 400 gallons. The facility also has an incinerator that can burn up to 20 gallons per hour.						

B. PROCESS DESIGN CAPACITY

LINE NUMBER	CODE (from list above)	1. AMOUNT (specify) 2. UNIT OF MEASURE (enter code)		FOR OFFICIAL USE ONLY			
X-1	S02	600	G				
X-2	T03	20	E				
1	T02	757,080	V				
2	D84	757,080	L				
3							
4							
5							
6							
7							
8							
9							
10							

C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESS (CODE "T04"). FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY.

T02. D84

The 216-B-63 Trench began waste management operation in March of 1970. The 216-B-63 Trench received corrosive dangerous waste from the regeneration of demineralizer columns in B Plant. Treatment occurred by the successive addition to the trench of acidic and caustic waste, which served to neutralize the waste while in the trench. Approximately 970,000 liters per day of total flow reached the trench. The corrosive discharges constitued a major part of this flow. Dangerous waste flows to the trench ceased in 1985 and all liquid flows to the trench ceased in 1992. The trench was covered with dirt in November 1994. The inlet pipe was filled with cement in December 1994. The trench can no longer accept dangerous waste. The current process capacity of the trench is zero based on the present configuration. The process design capacity listed in Section III.B reflects a historical value of the average total volume of liquid discharged rather than the current physical capacity of the unit.

IV. DESCRIPTION OF DANGEROUS WASTES

- A. DANGEROUS WASTE NUMBER Enter the four digit number from Chapter 173-303 WAC for each listed dangerous waste you will handle. If you handle dangerous wastes which are not listed in Chapter 173-303 WAC, enter the four digit number(s) that describe the characteristics and/or the toxic contaminants of those dangerous wastes
- B. ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

 ENGLISH UNIT OF MEASURE CODE

 METRIC UNIT OF MEASURE CODE

POUNDS P KILOGRAMS K
TONS T METRIC TONS M

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

D. PROCESSES

1. PROCESS CODES:

For listed dangerous waste: For each listed dangerous waste entered in column A select the code(s) from the list of process codes contained in Section III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed dangerous wastes: For each characteristic or toxic contaminant entered in Column A, select the code(s) from the list of process codes contained in Section III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed dangerous wastes that possess that characteristic or toxic contaminant.

Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: DANGEROUS WASTES DESCRIBED BY MORE THAN ONE DANGEROUS WASTE NUMBER - Dangerous wastes that can be described by more than one Waste Number shall be described on the form as follows:

- 1. Select one of the Dangerous Waste Numbers and enter it in column A. On the same line complete columns B, C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
- 2. In column A of the next line enter the other Dangerous Waste Number that can be used to describe the waste. In column D(2) on that line enter "Included with above" and make no other entries on that line.
- 3. Repeat step 2 for each other Dangerous Waste Number that can be used to describe the dangerous waste.

EXAMPLE FOR COMPLETING SECTION IV (shown in line numbers X-1, X-2, X-3, and X-4 below) - A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

L	A. DANGEROUS		OF MEA-SURE (enter code)	D. PROCESSES				
NO E.	WASTE NO.	B. ESTIMATED ANNUAL QUANTITY OF WASTE		1. PROCESS CODES (enter)			S	PROCESS DESCRIPTION (if a code is not entered in D(1))
X-1	K054	900	Р	T03	D80			
X-2	D002	400	P	T03	D80			
X-3	D001	100	P	T03	D80			
X-4	D002			T03	D80			included with above
1	D002	354,000,000	К	T02	D84			Surface Impoundment Neutralization/Percolation
2								
3								
4								
5								
6								
7								
8								
9								
10								

E. USE THIS SPACE TO LIST ADDITIONAL PROCESS CODES FROM SECTION D(1) ON PAGE 3.

	backwashes from annual basis.	n the regeneration of demineralizer columns in B Plant. Approximately 354,000,000 kilos of waste was managed in the trench on an
V. FACI	LITY DRAWING	Refer to attached drawing(s).
All exist	ing facilities must	include in the space provided on page 5 a scale drawing of the facility (see instructions for more detail).
VI. PHC	TOGRAPHS F	lefer to attached photograph(s).
		include photographs (arial or ground-level) that clearly delineate all existing structures; existing storage, treatment and disposal areas; and sites nt or disposal areas (see instructions for more detail).

or ruture storage, treatment or disposar area	s (see instructions for more detail).
VII. FACILITY GEOGRAPHIC LOCATION	This information is provided on the attached drawing(s) and photograph(s).

VII. FACILITY GEOGRAPHIC LOCATION	rilla illiorillation is p	vided on the attache	a diawing(s) and	photog	<i>μαριί(5)</i> .
LATITUDE (degrees,		LONGITUDE (degrees,	minutes, 8	& seconds)	


VIII. FACILITY OWNER						
A. If the facility owner is also the facility operator as listed below. B. If the facility owner is not the facility operator as listed	d in Section VII on Form 1, "General Information", place an " in Section VII on Form 1, complete the following items:	X" in the box	to the left and skip to Section IX			
1. NAME OF FACILITY'S LEGAL OWNER 2. PHONE NO. (area code & no.)						
3. STREET OR P.O. BOX	4. CITY OR TOWN	5. ST.	6. ZIP CODE			
IX. OWNER CERTIFICATION						
I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.						
NAME (print or type)	SIGNATURE	DATE SIGN	ED			
Keith A. Klein, Manager U.S. Department of Energy Richland Operations Office	Keith A. Klein	11/22/1999				
X. OPERATOR CERTIFICATION						
I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.						
NAME (print or type)	SIGNATURE	DATE SIGN	ED			
SEE ATTACHMENT						

X. OPERATOR CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

Keith A. Klein	11/22/99
Owner/Operator	Date
Keith A. Klein, Manager	
U.S. Department of Energy	
Richland Operations Office	
Michael C. Hughes	9/29/99
Co-Operator	Date
S. D. Leidle, President	
Bechtel Hanford, Inc.	


216-B-63 Trench Site Plan



H9502037.2

216-B-63 Trench, Rev. 5

216-B-63 TRENCH



46°33'46" 119°31'59"

95020800-6CN (PHOTO TAKEN 1995)